



RS7L4/0B

**4/0 Stranded Copper Conductor
to
#7 & Larger Reinforcing Bar**

Description

4/0 Stranded Copper Conductor to #7 & Larger Reinforcing Bar
Horizontal thru Cable to Side of Vertical Reinforcing Steel

(1) #CERPM3 Ceramic Packing Material required per weld

UltraShot Weld Metal	NUWTube Weld Metal	Mold Handle
US150	NUWTUBE150	MH1