



RE32/0B

**2/0 Stranded Copper Conductor
to
#3 Reinforcing Bar**

Description

2/0 Stranded Copper Conductor to #3 Reinforcing Bar
Tee of Vertical Thru Reinforcing Steel & Horizontal Tap Cable

(1) #WRPSLV Wrap Sleeve required per weld

UltraShot Weld Metal	NUWTube Weld Metal	Mold Handle
US115	NUWTUBE115	MH1