



RE7L6K

**#6 Stranded Copper Conductor
to
#7 & Larger Reinforcing Bar**

Description

#6 Stranded Copper Conductor to #7 & Larger Reinforcing Bar
Tee of Vertical Thru Reinforcing Steel & Horizontal Tap Cable

(1) #CERPM3 Ceramic Packing Material required per weld

UltraShot Weld Metal	NUWTube Weld Metal	Mold Handle
US45	NUWTUBE45	MH1